Product Change Notification

Change Notification #:   **116430 - 00**

Change Title: **Select Intel® Platform Controller Hubs,
PCN 116430-00,
Product Discontinuance,
End of Life**

Date of Publication: **August 18, 2018**

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins:	August 18, 2018
Last Product Discontinuance Order Date:	August 23, 2019
Orders for Discontinued Products Become Non-Cancelable:	August 23, 2019
Last Product Discontinuance Shipment Date:	February 21, 2020

Description of Change to the Customer:

Intel will discontinue the manufacturing of select products listed in the "Products Affected/Intel Ordering Codes" table below and the products will become unavailable for additional orders after August 23, 2019.

Customer Impact of Change and Recommended Action:

Please determine your remaining demand for the products listed in the "Products Affected/Intel Ordering Codes" table and place your "Last Product Discontinuance Order" in accordance with the "Key Milestones" listed above.

Functional Analysis Correlation Request (FA/CR) support for the products listed in the "Products Affected/Intel Ordering Codes" table will follow standard FA/CR support timelines.

Please contact your Intel Field Sales Representative with any questions, requests or concerns.

Products Affected / Intel Ordering Codes:

Marketing Name	Product Code	Platform	Spec Code	MM#
Intel® BD82QM67 Platform Controller Hub	BD82QM67	Mobile	SLJ4M	914325
Intel® BD82HM65 Platform Controller Hub	BD82HM65	Mobile	SLJ4P	914377
Intel® BD82B65 Platform Controller Hub	BD82B65	Desktop	SLJ4A	914379
Intel® BD82H61 Platform Controller Hub	BD82H61	Desktop	SLJ4B	914380
Intel® BD82Q67 Platform Controller Hub	BD82Q67	Desktop	SLJ4D	914397
Intel® BD82C206 Platform Controller Hub	BD82C206	Server	SLJ4G	914417

Intel® BD82QM77 Platform Controller Hub	BD82QM77	Mobile	SLJ8A	915663
Intel® BD82HM76 Platform Controller Hub	BD82HM76	Mobile	SLJ8E	915666
Intel® BD82Q77 Platform Controller Hub	BD82Q77	Desktop	SLJ83	915673
Intel® BD82B75 Platform Controller Hub	BD82B75	Desktop	SLJ85	915675
Intel® BD82C216 Platform Controller Hub	BD82C216	Server	SLJ8H	915680

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
August 18, 2018	00	Originally Published PCN

Product Change Notification
116430 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com
Asia Pacific/PRC Contact: apacgccb@intel.com
Europe Email: eccb@intel.com
Japan Email: jccb.ijkk@intel.com